

ActualVCE

- ✓ 24/7 customer support, Secure shopping site
- ✓ Free One year updates to match real exam scenarios
- ✓ If you failed your exam after buying our products we will refund the full amount back to you.

[Download Demo](#)



ONLINE TEST ENGINE
Online
Best Practice Material

- ✓ Online Tool, Convenient, easy to study.
- ✓ Instant Online Access
- ✓ Supports All Web Browsers
- ✓ Practice Online Anytime
- ✓ Test History and Performance Review
- ✓ Supports Windows / Mac / Android / iOS, etc.



DESKTOP TEST ENGINE
Soft
Best Practice Material

- ✓ Installable Software Application
- ✓ Simulates Real Exam Environment
- ✓ Builds Exam Confidence
- ✓ Supports MS Operating System
- ✓ Two Modes For Practice
- ✓ Practice Offline Anytime



PRACTICE PDF
PDF
Best Practice Material

- ✓ Printable PDF Format
- ✓ Prepared by IT Experts
- ✓ Instant Access to Download
- ✓ Study Anywhere, Anytime
- ✓ 365 Days Free Updates
- ✓ Free PDF Demo Available



Security & Privacy

ActualVCE respect customer privacy. We use McAfee's security service to provide you with utmost security for your personal information & peace of mind.



Instant Download

After Payment, our system will send you the products you purchase in mailbox in a minute after payment. If not received within 2 hours, please contact ActualVCE.



365 Days Free Updates

Free update is available within 365 days after your purchase. After 365 days, you will get 50% discounts for updating.



Try Before Buy

ActualVCE offers free demo of each product. You can check out the interface, question quality and usability of our practice exams before you decide to buy.

<http://www.actualvce.com/>

Believable Exam Dumps Questions grant you ensured success by your first attempt - ActualVCE

Exam : **D-PEMX-DY-23**

Title : Dell PowerEdge MX Modular
Deploy 2023 Exam

Vendor : EMC

Version : DEMO

NO.1 After installing a supported OS from a bootable ISO on an MX740c sled, an administrator discovers that not all the hardware is properly detected by the OS. They plan to reinstall the OS. What should the administrator do to resolve this issue through OS installation?

- A. Update the Dell OS Driver Pack and use the OS Deployment feature
- B. Modify the bootable ISO to remove faulty drivers and boot directly from the bootable ISO
- C. Modify the bootable ISO to remove faulty drivers and use the OS deployment feature
- D. Update the Dell OS Driver Pack and boot directly from the bootable ISO

Answer: D

NO.2 A company has several MX7000-systems, four FX2 solutions, one M1000e, and several PowerEdge rack servers.

Which management interface is recommended for managing this range of systems?

- A. OpenManage Modular, no optional plugins required
- B. OpenManage Essentials
- C. OpenManage Modular with optional plugins
- D. OpenManage Enterprise

Answer: D

NO.3 During the installation of a PowerEdge MX7000, the implementation engineer notices the PSU health indicator stay on for one second, blink five times, then shut off.

What is the issue?

- A. The PSU is faulty.
- B. There is a PSU mismatch.
- C. The PSU is performing firmware updates.
- D. There is no power to the PSU.

Answer: B

NO.4 A system administrator must carry out a SupportAssist log collection on an MX750c sled using iDRAC that includes operating system logs.

What is required?

- A. Enterprise License
- B. iDRAC LOM NIC
- C. OpenManage System Administrator
- D. iDRAC Service Module Driver installed

Answer: D

NO.5 What can be used as the firmware update source for OME-M within an MX chassis?

- A. Server Update Utility
Baseline from a Catalog
- B. Server Update Utility
System Live Image (SLI)
- C. Dell Update package
System Live Image (SLI)

D. Dell Update Package

Baseline from a Catalog

Answer: D

NO.6 What compute sled model best supports the following requirements?

4 Node Database Cluster Heavy transactional workload 16 Processors

24 TB of DDR4 Memory

40 TB of Disk Space Maximum of 200,000 IOPS

A. 4 x MX840C 16 Processors

24 TB of DDR4 Memory

40 TB of Disk Space based on SAS SSD Drives

B. 4 x MX840C 16 Processors

24 TB of DDR4 Memory

40 TB of Disk Space based on NVMe Drives

C. 8 x MX750C 16 Processors

16 TB of DDR4 Memory

45 TB of Disk Space based on NVMe Drives

D. 8 x MX740C 16 Processors

16 TB of DDR4 Memory

50 TB of Disk Space based on SAS SSD Drives

Answer: B

NO.7 How can a hard reset be performed on iDRAC?

A. On the iDRAC web interface, select the Reset option

B. Using the OME-M Interface and selecting Virtual Reseat

C. On the server, press and hold the ID LED button for 15 seconds

D. Using the RACADM command --SystemReset -t 0 -f

Answer: C

NO.8 An administrator has installed the iDRAC Service Module in the OS on a compute sled, they are unable to use its features in the iDRAC web GUI.

What is the likely cause of this issue?

A. OS to iDRAC pass-through feature is not enabled in the iDRAC

B. iDRAC Express license is installed

C. OS and iDRAC are configured on different networks

D. Installed OS is not supported

Answer: A

NO.9 A system administrator must interface the compute sleds of an MX7000 chassis to a Z9432F-ON in a single SmartFabric.

Which FEM IOM is required?

A. MX9116n

B. MX5108n

C. MX8116n

D. MX7116n

Answer: C

NO.10 Which is an invalid option for the PowerEdge MX7000 control panel?

A. LED with QuickSync 2

B. LCD with QuickSync 2

C. LED only

D. LCD only

Answer: A

NO.11 What is the minimum OME-M version required to use ATMOS?

A. 1.40.00

B. 2.00.00

C. 2.10.00

D. 1.60.50

Answer: B

NO.12 What are the correct CLI commands to configure the management IP Address on either the MX9116n or the MX5108n switches running SmartFabric OS10?

A. interface vlan 4020

no ip address

ip address 192.168.1.10/24

no shutdown

exit

management route 0.0.0.0/0 192.168.1.1

B. interface mgmt 1/1/1

no ip address

ip address 192.168.10.10/24

no shutdown

exit

management route 0.0.0.0/0 192.168.10.1

C. interface vlan 4020

no ip address

ip address 192.168.1.10/24

no shutdown

exit

interface mgmt 1/1/1

no ip address

ip address 192.168.1.10/24

no shutdown

exit

management route 0.0.0.0/0 192.168.1.1

D. interface vlan 4020

no ip address

```
ip address 192.168.10.10/24
no shutdown
exit
interface mgmt 1/1/1
no shutdown
exit
management route 0.0.0.0/0 192.168.10.1
```

Answer: C

NO.13 What does OBPARG allow on a PowerEdge MX750c?

- A. Run a compute sled with memory overclocking.
- B. Boot a compute sled with only one CPU.
- C. Run a compute sled with maximum performance.
- D. Boot a compute sled with reduced frequency.

Answer: D

NO.14 The MDB chassis tub assembly vertical distribution board provides connectivity to which chassis components?

- A. Five near fan modules
- B. Four cooling fans and four fabric I/O modules
- C. Power supplies, compute sleds, Management Modules, and two fabric I/O modules
- D. Four power supplies, compute sleds, Management Modules, and all fabric I/O modules

Answer: B